

STATE OF CONNECTICUT

CONNECTICUT HISTORICAL COMMISSION

9 South Prospect Street, Hartford, Connecticut 06106
(203) 566-3005

HISTORIC RESOURCES INVENTORY FORM

for Buildings and Structures

FOR OFFICE USE ONLY			
TOWN NO.:		SITE NO.:	
UTM: 18	/	/	/
QUAD:			
DISTRICT:	S	NR:	ACTUAL POTENTIAL

IDENTIFICATION

- 1. BUILDING NAME: Common: _____ Historic: Elisha Sears House
- 2. TOWN/CITY: Middletown VILLAGE: _____ COUNTY: Middlesex
- 3. STREET & NUMBER (and/or location): 112 East Main Street
- 4. OWNER(S): Russell M. and Mary E. Perking PUBLIC PRIVATE
- 5. USE: Present: Residence Historic: same
- 6. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: yes no
Interior accessible: yes, explain _____ no

DESCRIPTION

- 7. STYLE OF BUILDING: Italianate DATE OF CONSTRUCTION: c. 1860
- 8. MATERIAL(S) (indicate use or location when appropriate):
 clapboard asbestos siding brick
 wood shingle asphalt siding fieldstone
 board & batten stucco cobblestone
 aluminum siding concrete: type: _____ cut stone: type: brownstone
 other: _____ foundation
- 9. STRUCTURAL SYSTEM:
 wood frame: post and beam balloon (probably transitional)
 load bearing masonry structural iron or steel
 other: _____
- 10. ROOF: type:
 gable flat or low mansard monitor sawtooth
 gambrel shed hip hip round other _____
material:
 wood shingle roll asphalt tin slate
 asphalt shingle built up tile other: _____
- 11. NUMBER OF STORIES: 2 APPROXIMATE DIMENSIONS: 26'x30' (rear ell, 18'x41')
- 12. CONDITION: Structural: excellent good fair deteriorated
Exterior: excellent good fair deteriorated
- 13. INTEGRITY: Location: on original site moved, when: _____
Alterations: no yes, explain: Rear addition; north addition and porches; asbestos
- 14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES: siding over clapboards
 barn shed garage other landscape features or buildings: _____
 carriage house shop garden _____
- 15. SURROUNDING ENVIRONMENT:
 open land woodland residential scattered buildings visible from site
 commercial industrial rural high building density

16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: This residence on East Main Street is near the intersection of Chestnut Street and Cooley Avenue. Its large size and bold rectangular design make it an apparent feature on the street. The structure contrasts with the neighboring houses and commercial buildings. Flanked by a brick commercial structure south and an overgrown lot north, it faces a service station and an early three-story factory building across the street.

17. OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and/or exterior):

SIGNIFICANCE

Architect: _____

Builder: _____

18. HISTORICAL OR ARCHITECTURAL IMPORTANCE: This residence, first owned by Elisha Sears, may have been erected soon after the property was mortgaged in 1854. Sears taught school for many years in the Hubbard and South Farms Districts. The house, exhibiting a large rectangular profile, is of the Italianate style. It features a wide cornice with dentils displayed on the frieze beneath and a distinctive narrow cupola. Like the roof of the building, the cupola has an unusually wide cornice. It is further decorated by thin scrolled brackets and small ogee-like, arched windows.

This building, one of the largest Italianate houses in the South Farms area, is an integral East Main Street feature. It is representative of a style popular in the vicinity during the 1860s and 70s when a large increase in residential development occurred, corresponding with the district's industrial growth. East Main Street and nearby Silver Street developed earlier than the surrounding roads. Consequently, the residence may have been one of the first Italianate buildings constructed in South Farms, where a large concentration of this style remain.

PHOTOGRAPH

photographer: Robert Svec

date: 6/78 view: west

negative on file: Roll 27, #8

COMPILED BY:

name: Robert Svec date: 6/78

organization: Greater Middletown Preservation Trust

address: 27 Washington St., Middletown, Ct. 06457

19. SOURCES: Middletown Land Records; Beers Atlas, 1874; Bailey Map, 1877; Walling Map, 1859; Commemorative Biographical Record of Middlesex County (Chicago: J.B. Beers, 1903)



20. SUBSEQUENT FIELD EVALUATIONS:

21. THREATS TO BUILDING OR SITE:

none known highways vandalism developers other: _____
 renewal private deterioration zoning explanation: _____