

STATE OF CONNECTICUT

CONNECTICUT HISTORICAL COMMISSION

59 South Prospect Street, Hartford, Connecticut 06106
(203) 566-3005

HISTORIC RESOURCES INVENTORY FORM

For Buildings and Structures

FOR OFFICE USE ONLY

TOWN NO.: SITE NO.:
UTM: 18 / - / - / - / - / -
QUAD:
DISTRICT: S NR: ACTUAL
POTENTIAL

IDENTIFICATION

- 1. BUILDING NAME: Common: Baptist Church Historic: same
- 2. TOWN/CITY: Middletown VILLAGE: COUNTY: Middlesex
- 3. STREET & NUMBER (and/or location): 93 Main Street
- 4. OWNER(S): First Baptist Church PUBLIC PRIVATE
- 5. USE: Present: Church Historic: same
- 6. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: yes no
Interior accessible: yes, explain religious services no

DESCRIPTION

- 7. STYLE OF BUILDING: Greek Revival DATE OF CONSTRUCTION: 1842
- 8. MATERIAL(S) (indicate use or location when appropriate):
 clapboard asbestos siding brick
 wood shingle asphalt siding fieldstone
 board & batten stucco cobblestone
 aluminum siding concrete: type: cut stone: type: brownstone foundation
 other:
- 9. STRUCTURAL SYSTEM:
 wood frame: post and beam balloon
 load bearing masonry structural iron or steel
 other:
- 10. ROOF: type:
 gable flat mansard monitor sawtooth
 gambrel shed hip round other
material:
 wood shingle roll asphalt tin slate
 asphalt shingle built up tile other:
- 11. NUMBER OF STORIES: 2 APPROXIMATE DIMENSIONS: 75'x56'
- 12. CONDITION: Structural: excellent good fair deteriorated
Exterior: excellent good fair deteriorated
- 13. INTEGRITY: Location: on original site moved, when:
Alterations: no yes, explain: Portico and small rear addition; belfry removed
- 14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES:
 barn shed garage other landscape features or buildings:
 carriage house shop garden
- 15. SURROUNDING ENVIRONMENT:
 open land woodland residential scattered buildings visible from site
 commercial industrial rural high building density
- 16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: This large brick structure, set on a corner site, is located in Middletown's Metro South Redevelopment-Restoration area. Across from Spear Park and next to three recently restored early homes, this building is the dominant element of the immediate area.

STATE OF CONNECTICUT

CONNECTICUT HISTORICAL COMMISSION

59 South Prospect Street, Hartford, Connecticut 06106
(203) 566-3005

HISTORIC RESOURCES INVENTORY FORM

For Buildings and Structures

FOR OFFICE USE ONLY			
TOWN NO.:	SITE NO.:		
UTM: 18/	/	/	/
QUAD:			
DISTRICT:	S	NR:	ACTUAL POTENTIAL

IDENTIFICATION

- 1. BUILDING NAME: Common: Baptist Church Historic: same
- 2. TOWN/CITY: Middletown VILLAGE: _____ COUNTY: Middlesex
- 3. STREET & NUMBER (and/or location): 93 Main Street
- 4. OWNER(S): First Baptist Church PUBLIC PRIVATE
- 5. USE: Present: Church Historic: same
- 6. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: yes no
Interior accessible: yes, explain religious services no

DESCRIPTION

- 7. STYLE OF BUILDING: Greek Revival DATE OF CONSTRUCTION: 1842
- 8. MATERIAL(S) (indicate use or location when appropriate):
 clapboard asbestos siding brick
 wood shingle asphalt siding fieldstone
 board & batten stucco cobblestone
 aluminum siding concrete: type: _____ cut stone: type: brownstone
 other: _____ foundation
- 9. STRUCTURAL SYSTEM:
 wood frame: post and beam balloon
 load bearing masonry structural iron or steel
 other: _____
- 10. ROOF: type:
 gable flat mansard monitor sawtooth
 gambrel shed hip round other _____
 material:
 wood shingle roll asphalt tin slate
 asphalt shingle built up tile other: _____
- 11. NUMBER OF STORIES: 2 APPROXIMATE DIMENSIONS: 75'x56'
- 12. CONDITION: Structural: excellent good fair deteriorated
 Exterior: excellent good fair deteriorated
- 13. INTEGRITY: Location: on original site moved, when: _____
 Alterations: no yes, explain: Portico and small rear addition; belfry removed
- 14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES:
 barn shed garage other landscape features or buildings: _____
 carriage house shop garden _____
- 15. SURROUNDING ENVIRONMENT:
 open land woodland residential scattered buildings visible from site
 commercial industrial rural high building density

16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: This large brick structure, set on a corner site, is located in Middletown's Metro South Redevelopment-Restoration area. Across from Spear Park and next to three recently restored early homes, this building is the dominant element of the immediate area.

STATE OF CONNECTICUT
CONNECTICUT HISTORICAL COMMISSION
59 South Prospect Street, Hartford, Connecticut 06106
HISTORIC RESOURCES INVENTORY FORM
For Buildings and Structures

FOR OFFICE USE ONLY
TOWN NO.: _____ SITE NO.: _____
UTM: 18 / - / - / - / - / -
QUAD: _____
DISTRICT: S NR: ACTUAL
POTENTIAL

CONTINUATION SHEET
Item number: _____ Date: 1/90

Baptist Church
93 Main Street, Middletown, CT 06457

