TATE OF CONNECTICUT

CONNECTICUT HISTORICAL COMMISSION

59 South Prospect Street, Hartford, Connecticut 06106 03) 566-3005

HISTORIC RESOURCES INVENTORY FORM

For Buildings and Structures

TOWN NO.:			TE NO.:
UTM: 18/_	//-	/	-/
QUAD:		•	
	_	NR:	ACTUAL
DISTRICT:	3	La Le +	MOIONE

DENTIFICATION
1. BUILDING NAME: Common: Richard E. Cody Shoes Historic: Ward-Cody Building
2. TOWN/CITY: Middletown VILLAGE: COUNTY: Middlesex
3. STREET & NUMBER (and/or location): 502-508 Main Street
4. OWNER(S):Edward D. and Catherine E. CodyPUBLIC_X PRIVATE
5. USE: Present: Commercial Historic: same
6. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: x yes no Interior accessible: x yes, explain commercial use no
ESCRIPTION
7. STYLE OF BUILDING: Victorian Commercial DATE OF CONSTRUCTION: 1889-1890
8. MATERIAL(S) (indicate use or location when appropriate): clapboard
9. STRUCTURAL SYSTEM: wood frame:post and beamballoon _x load bearing masonrystructural iron or steel other:
10. ROOF: type: gablex flatmansardmonitorsawtoothgambrelshedhiproundother material:wood shingleroll asphalt tinslateasphalt shingle x_built uptileother:
11. NUMBER OF STORIES: 3 APPROXIMATE DIMENSIONS: 42'x61'
12. CONDITION: Structural:excellentgoodfairdeteriorateddeteriorateddeteriorated
13. INTEGRITY: Location: x on original site moved, when: Alterations: no x yes, explain: South storefront altered
14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES: barnshed garageother landscape features or buildings:carriage houseshop garden
15. SURROUNDING ENVIRONMENT: open landwoodland residential scattered buildings visible from site x high building density
16 INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: The Ward-Cody building is located

16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: The Ward-Cody building is located toward the north end of Main Street. This area consists primarily of two to three story commercial structures constructed in the late 19th century and early 20th century. Directly to the north of the Ward-Cody Building is an early-20th century, two-story, Classical Revival commercial structure and to the south is a one-story contemporary retail building.

North storefront, brackets			
Sign "Richard E. Cody Shoes"			
	•		
	•		
CAMPLICANICE			
GIGNIFICANCE Architect:B	uilder:		
18. HISTORICAL OR ARCHITECTURAL IMPORTANCE:		uilding, 502-508	Main Street
was built in 1889 or 1890 by George N. Ward. Ge	eorge N. Ward w	as a prominent, n	ative bus-
inessman who served on various bank boards. He	was responsibl	e for much of the	commercial
development of the north end of Main Street in t	the late 19th c	entury. The buil	ding was
nurchased in 1919 by Richard E. Cody, who operat	ted "Richard E.	Cody Shoes" here	. It is
still owned by the Cody family. Small retail fi	irms have been	located in this b	uilding
Alternative to the state of the	the state of the s		
The Ward-Cody building is a good example of a ing. It is three stories in height and contains	e eis mingume v. Tane-Tânu ceur	n each floor. De	corative
and a succession of the company of the company and a	anched windows	eybibiting detail	ing. Ine
early north store front of "Richard E. Cody Shoe	es." probably d	ating from the ea	rly 20th ce
tury, is still intact. Two curved bays rest on the	bases sheathed	with copper. The	signboard
and cornice of the storefront are also of copper	r. and display	the legend "Richa	rd E. Cody
Shoes." That storefront is an important surviva	al of an early	20th century trea	tment of a
commercial facade.			
		<i></i>	
PHOTOGRAPH		3	\nearrow
photographer: Elizabeth Loomis			
date: 10/78 view: east			
negative on file: Roll 46, #2-2A		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
COMPILED BY: David Engstrom date: 1/79	o — J	a fi	
organization: Greater Middletown Preservation Trus	st 🕻 🕫		
address: 27 Washington St., Middletown, Ct. 0645	57 g		-
address: nabilitieson both		the crappa	J BR
19 SOURCES: Middletown Land Records; Middletown		Tillullillillillillillillillillillillilli	
City Directories; Biographical Record of Middle-	-		
sex County (Chicago: J.H. Beers, 1903)			
		FERN	J
20. SUBSEQUENT FIELD EVALUATIONS:			
			Committee of the control of the cont
		•	
21. THREATS TO BUILDING OR SITE:	,		
x none knownhighways vandalism		other:	
renewalprivatedeterioration	zoning 6	explanation:	

___renewal

17. OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and/or exterior):

STATE OF CONNECTICUT

CONNECTICUT HISTORICAL COMMISSION
59 South Prospect Street, Hartford, Connecticut 06106

HISTORIC RESOURCES INVENTORY FORM For Buildings and Structures

•	
CONTINUATION	CHEET
CONTINUATION	SHEEL

00,111110/1110	711 211		
Item number:	Date:	1/90	

TOWN NO.:		,S1*	TE NO.:
UTM: 18/_	//-	/	-//
		- 1	•
QUAD:		-	
QUAD: '	s	NR:	ACTUAL

Ward-Cody Building
502-508 Main Street, Middletown, CT 06457

